


## PL-5900 Series Windows 2000 LAN Driver Installation Procedure

Please be sure to read this explanation completely to ensure the correct use of this product.


1. Click on the [Start] button, then [Settings], then [Control Panel]




2. Click on the [Control Panel]'s [Administrative Tools] icon.



3. Click on the [Computer Management] icon.




4. Click on the [Other Device] item's [Ethernet Controller] selection's Property button. Then, click on the [Driver] tab's [Reinstall Driver] button.




5. When the [Upgrade Device Driver Wizard] screen appears, click on [Next].



6. Click on the [Search for a suitable driver for my device (recommended)] selection and then on [Next].




7. Click on [Specify a location] and then on [Next].



8. Enter the location of the LAN driver in the [Copy manufacturer's files from:] window, and click on [OK].



9. Click on [Next].



10. Click on [Finish] and then re-start your PC.

